



Ko te ahua he whakaahua.
Tirohia nga whakaritenga mo nga taipitopito hua.

AD8120ACPZ-RL

Tau Wae: **AD8120ACPZ-RL**
 Whakaahuatanga Hua: IC ANLG VIDEO DELAY LINE 32LFCSP
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS
 Ngā Rauemi: [AD8120ACPZ-RL.pdf](#)

Kaihanga / Waitohu: ADI (Analog Devices, Inc.)
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

[TUKUNA HE UIUI](#)

Taipitopito hua

Tau Wae	AD8120ACPZ-RL	Kaihanga	ADI (Analog Devices, Inc.)
Whakaahuatanga	IC ANLG VIDEO DELAY LINE 32LFCSP	Whakahaere Toko Whakahaere / RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Pepa Raraunga	AD8120ACPZ-RL.pdf		
Momo	Video Delay Line	Pūrere Pūrere Whakarato	32-LFCSP-VQ (5x5)
Raupapa	-	Packaging	Tape & Reel (TR)
Paa / Case	32-VFQFN Exposed Pad, CSP	Momo Tae	Surface Mount
Taumata Whakaaro Moe (MSL)	3 (168 Hours)	Te Tae Kaituku Taeke	8 Weeks
Whakahaere Toko Whakahaere / RoHS Tūnga	Lead free / RoHS Compliant	Tau Wae Tuakiri	AD8120
Nga tono	HD Video		

Hua e Hono ana

<p>AD8122ACPZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC RCVR TRPL DIFF EQUAL 40LFCSP Tikiake: AD8122ACPZ.pdf</p> <p>RFQ</p>	<p>AD811JRZ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC OPAMP VIDEO HP 8SOIC Tikiake: AD811JRZ-REEL7.pdf</p> <p>RFQ</p>
<p>AD8123ACPZ-RL Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC RCVR TRPL DIFF EQUAL 40LFCSP Tikiake: AD8123ACPZ-RL.pdf</p> <p>RFQ</p>	<p>AD8120ACPZ-R2 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC ANLG VIDEO DELAY LINE 32LFCSP Tikiake: AD8120ACPZ-R2.pdf</p> <p>RFQ</p>
<p>AD811SQ/883B Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC OPAMP VID HPERFORM 8CERDIP Tikiake: AD811SQ/883B.pdf</p> <p>RFQ</p>	<p>AD8124ACPZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC HS RCVR EQUALIZER 40LFCSP Tikiake: AD8124ACPZ.pdf</p> <p>RFQ</p>
<p>AD811JRZ-REEL Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC OPAMP VIDEO HP 8SOIC Tikiake: AD811JRZ-REEL.pdf</p> <p>RFQ</p>	<p>AD8123ACPZ-R7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC RCVR TRPL DIFF EQUAL 40LFCSP Tikiake: AD8123ACPZ-R7.pdf</p> <p>RFQ</p>
<p>AD811SE/883B Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC OPAMP VID HPERFORM 20CLCC Tikiake: AD811SE/883B.pdf</p> <p>RFQ</p>	<p>AD8123ACPZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC RCVR TRPL DIFF EQUAL 40LFCSP Tikiake: AD8123ACPZ.pdf</p> <p>RFQ</p>
<p>AD8122ACPZ-R7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC RCVR TRPL DIFF EQUAL 40LFCSP Tikiake: AD8122ACPZ-R7.pdf</p> <p>RFQ</p>	<p>AD8120ACPZ-R7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC ANLG VIDEO DELAY LINE 32LFCSP Tikiake: AD8120ACPZ-R7.pdf</p> <p>RFQ</p>

Nga tohu e pa ana

ADI (Analog Devices, Inc.) AD8120ACPZ-RL	AD8120ACPZ-RL Kaitoha	AD8120ACPZ-RL Kaiwhakarato
AD8120ACPZ-RL Utu	AD8120ACPZ-RL Nga Whakaahua	AD8120ACPZ-RL Whakaahua
Pukaiti PDF AD8120ACPZ-RL PDF	AD8120ACPZ-RL Tangohia te Pukaiti	Pukaiti AD8120ACPZ-RL
AD8120ACPZ-RL Stock	Hokona AD8120ACPZ-RL	Hokona ADI (Analog Devices, Inc.) AD8120ACPZ-RL
ADI (Analog Devices, Inc.) AD8120ACPZ-RL	ADI (Analog Devices, Inc.) Kaiwhakarato	Kaitoha ADI (Analog Devices, Inc.)
ADI (Analog Devices, Inc.) AD8120ACPZ-RL	AD AD8120ACPZ-RL	ADI (Analog Devices, Inc.) AD8120ACPZ-RL
Analog Devices Inc. AD8120ACPZ-RL	Analog Devices, Inc. AD8120ACPZ-RL	