

LMX2485QSQ/NOPB

Tau Wae: **LMX2485QSQ/NOPB**

Whakaahuatanga Hua: IC FREQ SYNTH 3GHZ 24WQFN

RoHs Tūnga: Whakahaerehia te kore utu / RoHS


Ngā Rauemi:

Kaihanga / Waitohu: N/A

Tuhinga mai i: Hong Kong

Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

 TUKUNA HE UIUI >















Ko te ahua he whakaahua.
Tirohia nga whakaritenga mo nga taipitopito hua.

Taipitopito hua

Tau Wae	LMX2485QSQ/NOPB	Kaihanga	N/A
Whakaahuatanga	IC FREQ SYNTH 3GHZ 24WQFN	Whakahaere Toko Whakahaere / RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Pepa Raraunga			
Tuhinga o mua	2.5 V ~ 3.6 V	Momo	Frequency Synthesizer (RF)
Pūre Pūre Whakarato	24-WQFN (4x4)	Raupapa	PLLatinum™
Ratonga - Whakauru: Whakaputa	3:2	Packaging	Tape & Reel (TR)
Paa / Case	24-WFQFN Exposed Pad	PLL	Yes
Whakaputa	Clock	Tae Mahi	-40°C ~ 105°C
Tuhinga o mua	1	Momo Tae	Surface Mount
Taumata Whakaaro Moe (MSL)	3 (168 Hours)	Te Tae Kaituku Taeke	20 Weeks
Whakahaere Toko Whakahaere / RoHS Tūnga	Lead free / RoHS Compliant	Whakauru	Clock
Tautanga - Max	3.1GHz	Kawewehe / Whakanao	Yes/Yes
Motuhake - Whakauru: Whakaputa	Yes/No	Tau Wae Tuakiri	LMX2485

Hua e Hono ana

 <p>LMX2485ESQX/NOPB Kaihanga: N/A Whakaahuatanga: IC FREQUENCY SYNTHESIZER 24WQFN</p> <p>RFQ</p>	 <p>LMX2485SQ/NOPB Kaihanga: N/A Whakaahuatanga: IC PLL FREQ SYNTH 3GHZ 24WQFN</p> <p>RFQ</p>
 <p>LMX2486SQ/NOPB Kaihanga: N/A Whakaahuatanga: IC FREQ SYNTH 4.5GHZ 24WQFN</p> <p>RFQ</p>	 <p>LMX2485E EVAL Kaihanga: N/A Whakaahuatanga: BOARD EVALUATION LMX2485E</p> <p>RFQ</p>
 <p>LMX2485E EVAL/NOPB Kaihanga: N/A Whakaahuatanga: EVAL BOARD FOR LMX2485E</p> <p>RFQ</p>	 <p>LMX2470SLEX/NOPB Kaihanga: N/A Whakaahuatanga: IC PLL DELTA-SIGMA 24LAMUCSP</p> <p>RFQ</p>
 <p>LMX2485SQX/NOPB Kaihanga: N/A Whakaahuatanga: IC FREQ SYNTH 3GHZ 24WQFN</p> <p>RFQ</p>	 <p>LMX2485QSQX/NOPB Kaihanga: N/A Whakaahuatanga: IC FREQ SYNTH 3GHZ 24WQFN</p> <p>RFQ</p>
 <p>LMX2486SQ/NOPB Kaihanga: N/A Whakaahuatanga: IC PLL FREQ SYNTH 1-4.5GHZ 24QFN</p> <p>RFQ</p>	 <p>LMX2471SLEX Kaihanga: N/A Whakaahuatanga: IC PLL LP 3.6GHZ/1.7GHZ 24-CSP</p> <p>RFQ</p>
 <p>LMX2486EVAL Kaihanga: N/A Whakaahuatanga: BOARD EVAL FOR LMX2486</p> <p>RFQ</p>	 <p>LMX2485ESQ/NOPB Kaihanga: N/A Whakaahuatanga: IC PLL FREQ SYNTH 3GHZ 24WQFN</p> <p>RFQ</p>

Nga tohu e pa ana

LMX2485QSQ/NOPB

LMX2485QSQ/NOPB Utu

Pukaiti PDF LMX2485QSQ/NOPB PDF

LMX2485QSQ/NOPB Stock

LMX2485QSQ/NOPB

LMX2485QSQ/NOPB Kaitoha

LMX2485QSQ/NOPB Nga Whakaahua

LMX2485QSQ/NOPB Tangohia te Pukaiti

Hokona LMX2485QSQ/NOPB

Kaiwhakarato

LMX2485QSQ/NOPB Kaiwhakarato

LMX2485QSQ/NOPB Whakaahua

Pukaiti LMX2485QSQ/NOPB

Hokona LMX2485QSQ/NOPB

Kaitoha