

CD40109BQNSRQ1

Tau Wae: **CD40109BQNSRQ1**

Whakaahuatanga Hua: IC TRNSLTR UNIDIRECTIONAL 16SO

RoHs Tūnga: Whakahaerehia te kore utu / RoHS


Ngā Rauemi:

Kaihanga / Waitohu: N/A

Tuhinga mai i: Hong Kong

Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

 TUKUNA HE UIUI >















Ko te ahua he whakaahua.
Tirohia nga whakaritenga mo nga taipitopito hua.

Taipitopito hua

Tau Wae	CD40109BQNSRQ1	Kaihanga	N/A
Whakaahuatanga	IC TRNSLTR UNIDIRECTIONAL 16SO	Whakahaere Toko Whakahaere / RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Pepa Raraunga			
Putanga - VCCB	3V ~ 18V	Putanga - VCCA	3V ~ 18V
Momo Kuputuhi	Voltage Level	Pūrere Pūrere Whakarato	16-SO
Raupapa	Automotive, AEC-Q100, 4000B	Packaging	Original-Reel®
Paa / Case	16-SOIC (0.209", 5.30mm Width)	Momo putanga	Tri-State, Non-Inverted
Waitohu Whakaputa	-	Ētahi Ingoa	296-36573-6
Tae Mahi	-40°C ~ 125°C (TA)	Tuhinga o mua	4
Momo Tae	Surface Mount	Taumata Whakaaro Moe (MSL)	1 (Unlimited)
Te Tae Kaituku Taeke	6 Weeks	Whakahaere Toko Whakahaere / RoHS Tūnga	Lead free / RoHS Compliant
Waitohu Whakauru	-	Ngā āhuatanga	-
Whakaahuatanga Taipitopito	Voltage Level Translator Unidirectional 4 Circuit 1 Channel 16-SO	Raraunga Raraunga	-
Herenga ma te Kaapene	1	Momo Channel	Unidirectional
Tau Wae Tuakiri	40109		

Hua e Hono ana

 <p>CD4010BM96E4 Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16SOIC</p> <p>RFQ</p>	 <p>CD40109BPWR Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIR 16TSSOP</p> <p>RFQ</p>
 <p>CD4010BM96 Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16SOIC</p> <p>RFQ</p>	 <p>CD4010BM Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16SOIC</p> <p>RFQ</p>
 <p>CD40109BPW Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIR 16TSSOP</p> <p>RFQ</p>	 <p>CD40109BPWRG4 Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIR 16TSSOP</p> <p>RFQ</p>
 <p>CD40109BPWRE4 Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIR 16TSSOP</p> <p>RFQ</p>	 <p>CD4010BEG4 Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16DIP</p> <p>RFQ</p>
 <p>CD40109BNSRG4 Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIRECTIONAL 16SO</p> <p>RFQ</p>	 <p>CD40109BPWG4 Kaihanga: N/A Whakaahuatanga: IC TRNSLTR UNIDIR 16TSSOP</p> <p>RFQ</p>
 <p>CD4010BE Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16DIP</p> <p>RFQ</p>	 <p>CD4010BM96G4 Kaihanga: N/A Whakaahuatanga: IC BUFFER NON-INVERT 18 V 16SOIC</p> <p>RFQ</p>

Nga tohu e pa ana

CD40109BQNSRQ1

CD40109BQNSRQ1 Utu

Pukaiti PDF CD40109BQNSRQ1 PDF

CD40109BQNSRQ1 Stock

CD40109BQNSRQ1

CD40109BQNSRQ1 Kaitoha

CD40109BQNSRQ1 Nga Whakaahua

CD40109BQNSRQ1 Tangohia te Pukaiti

Hokona CD40109BQNSRQ1

Kaiwhakarato

CD40109BQNSRQ1 Kaiwhakarato

CD40109BQNSRQ1 Whakaahua

Pukaiti CD40109BQNSRQ1

Hokona CD40109BQNSRQ1

Kaitoha