

## UC3872DW

Tau Wae: **UC3872DW**

Whakaahuatanga Hua: IC LAMP BALLAST CNTRLR 16-SOIC

RoHs Tūnga: Whakahaerehia te kore utu / RoHS

Ngā Rauemi:

Kaihanga / Waitohu: N/A

Tuhinga mai i: Hong Kong

Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

 TUKUNA HE UIUI >















Ko te ahua he whakaahua.  
Tirohia nga whakaritenga mo nga taipitopito hua.

### Taipitopito hua

<b>Tau Wae</b>	UC3872DW	<b>Kaihanga</b>	N/A
<b>Whakaahuatanga</b>	IC LAMP BALLAST CNTRLR 16-SOIC	<b>Whakahaere Toko Whakahaere / RoHS Tūnga</b>	Whakahaerehia te kore utu / RoHS
<b>Pepa Raraunga</b>			
<b>Tuhinga o mua</b>	4.5 V ~ 24 V	<b>Momo</b>	Ballast Controller
<b>Pūrere Pūrere Whakarato</b>	16-SOIC	<b>Raupapa</b>	-
<b>Packaging</b>	Tube	<b>Paa / Case</b>	16-SOIC (0.295", 7.50mm Width)
<b>Ētahi Ingoa</b>	296-11328-5	<b>Tae Mahi</b>	0°C ~ 70°C
<b>Momo Tae</b>	Surface Mount	<b>Taumata Whakaaro Moe (MSL)</b>	2 (1 Year)
<b>Te Tae Kaituku Taeke</b>	8 Weeks	<b>Whakahaere Toko Whakahaere / RoHS Tūnga</b>	Lead free / RoHS Compliant
<b>Rautanga</b>	57kHz ~ 78kHz	<b>Te whakaheke</b>	No
<b>I teie nei - Te tuku</b>	6mA	<b>I teie nei - Taputapu Whakaputa / Miihini</b>	-
<b>Tau Wae Tuakiri</b>	UC3872		

### Hua e Hono ana

 <p><b>UC3872DWTRG4</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CONTROLR 16SOIC</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3871DWG4</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRVR 18SOIC</p> <p><a href="#">RFQ</a></p>
 <p><b>UC3872DWTR</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CONTROLR 16SOIC</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3872MTR</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CONTROLR 16SSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>UC3872MG4</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CONTROLR 16SSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3871N</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRVR 18-DIP</p> <p><a href="#">RFQ</a></p>
 <p><b>UC3872M</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CNTRLR 16SSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3871NG4</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRIVER 18DIP</p> <p><a href="#">RFQ</a></p>
 <p><b>UC3871Q</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRVR 20PLCC</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3871QG3</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRVR 20PLCC</p> <p><a href="#">RFQ</a></p>
 <p><b>UC3871DWTR</b> Kaihanga: N/A Whakaahuatanga: IC FLUORESCENT LAMP DRVR 18SOIC</p> <p><a href="#">RFQ</a></p>	 <p><b>UC3872DWG4</b> Kaihanga: N/A Whakaahuatanga: IC LAMP BALLAST CONTROLR 16SOIC</p> <p><a href="#">RFQ</a></p>

### Nga tohu e pa ana

UC3872DW	UC3872DW Kaitoha	UC3872DW Kaiwhakarato
UC3872DW Utu	UC3872DW Nga Whakaahua	UC3872DW Whakaahua
Pukaiiti PDF UC3872DW PDF	UC3872DW Tangohia te Pukaiiti	Pukaiiti UC3872DW
UC3872DW Stock	Hokona UC3872DW	Hokona UC3872DW
UC3872DW	Kaiwhakarato	Kaitoha