

CDCS501PWR

Tau Wae: **CDCS501PWR**

Whakaahuatanga Hua: IC CLOCK GEN/BUFFER SSC 8TSSOP

RoHs Tūnga: Whakahaerehia te kore utu / RoHS

Ngā Rauemi:

Kaihanga / Waitohu: N/A

Tuhinga mai i: Hong Kong

Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

 TUKUNA HE UIUI >















Ko te ahua he whakaahua.
Tirohia nga whakaritenga mo nga taipitopito hua.

Taipitopito hua

Tau Wae	CDCS501PWR	Kaihanga	N/A
Whakaahuatanga	IC CLOCK GEN/BUFFER SSC 8TSSOP	Whakahaere Toko Whakahaere / RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Pepa Raraunga			
Tuhinga o mua	3 V ~ 3.6 V	Momo	Clock Generator
Pūrere Pūrere Whakarato	8-TSSOP	Raupapa	-
Ratonga - Whakauru: Whakaputa	1:1	Packaging	Cut Tape (CT)
Paa / Case	8-TSSOP (0.173", 4.40mm Width)	PLL	No
Whakaputa	LVC MOS	Ētahi Ingoa	296-24443-1
Tae Mahi	-40°C ~ 85°C	Tuhinga o mua	1
Momo Tae	Surface Mount	Taumata Whakaaro Moe (MSL)	1 (Unlimited)
Te Tae Kaituku Taeke	8 Weeks	Whakahaere Toko Whakahaere / RoHS Tūnga	Lead free / RoHS Compliant
Whakauru	LVC MOS	Tautanga - Max	108MHz
Kawewehe / Whakanao	No/No	Motuhake - Whakauru: Whakaputa	No/No
Tau Wae Tuakiri	CDCS501		

Hua e Hono ana

 <p>CDCR83ADBQRG4 Kaihanga: N/A Whakaahuatanga: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>	 <p>CDCS503PWR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>
 <p>CDCS503PW Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>	 <p>CDCR83DBQR Kaihanga: N/A Whakaahuatanga: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>
 <p>CDCS503TPWRQ1 Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:1 108MHZ 8TSSOP</p> <p>RFQ</p>	 <p>CDCR83DBQ Kaihanga: N/A Whakaahuatanga: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>
 <p>CDCS502PERF-EVM Kaihanga: N/A Whakaahuatanga: EVAL PERFORMANCE MOD FOR CDCS502</p> <p>RFQ</p>	 <p>CDCS502PWR Kaihanga: N/A Whakaahuatanga: IC OSC CLOCK GENERATOR 8-TSSOP</p> <p>RFQ</p>
 <p>CDCS502PW Kaihanga: N/A Whakaahuatanga: IC OSC CLOCK GENERATOR 8-TSSOP</p> <p>RFQ</p>	 <p>CDCS501PW Kaihanga: N/A Whakaahuatanga: IC CLK GEN/BUFF SSC 3.3V 8TSSOP</p> <p>RFQ</p>
 <p>CDCR83DBQG4 Kaihanga: N/A Whakaahuatanga: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>	 <p>CDCR83DBQRG4 Kaihanga: N/A Whakaahuatanga: IC DIRECT RAMBUS CLK GEN 24-QSOP</p> <p>RFQ</p>

Nga tohu e pa ana

CDCS501PWR

CDCS501PWR Utu

Pukaiti PDF CDCS501PWR PDF

CDCS501PWR Stock

CDCS501PWR

CDCS501PWR Kaitoha

CDCS501PWR Nga Whakaahua

CDCS501PWR Tangohia te Pukaiti

Hokona CDCS501PWR

Kaiwhakarato

CDCS501PWR Kaiwhakarato

CDCS501PWR Whakaahua

Pukaiti CDCS501PWR

Hokona CDCS501PWR

Kaitoha