



IDT5V9885BPFI

Tau Wae: **IDT5V9885BPFI**

Whakaahuatanga Hua: IC CLK GEN 3.3V EEPROM 32-TQFP

RoHS Tūnga: Kei roto nga rangatira / RoHS kaore i te ture

Ngā Rauemi: IDT5V9885BPFI.pdf

Kaihanga / Waitohu: **IDT (Integrated Device Technology)**

Tuhinga mai i: Hong Kong

Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TUKUNA HE UIUI >

Ko te ahua he whakaahua.
Tirohia nga whakaritenga mo nga taipitopito hua.

Taipitopito hua

Tau Wae	IDT5V9885BPFI	Kaihanga	IDT (Integrated Device Technology)
Whakaahuatanga	IC CLK GEN 3.3V EEPROM 32-TQFP	Whakaheere Toko Whakaheere / RoHS Tūnga	Kei roto nga rangatira / RoHS kaore i te ture
Pepa Raraunga	IDT5V9885BPFI.pdf		
Tuhinga o mua	3.135 V ~ 3.6 V	Momo	Clock Generator
Pūre Pūre Whakarato	32-TQFP (7x7)	Raupapa	-
Ratonga - Whakauru: Whakaputa	2:8	Packaging	Tray
Paa / Case	32-LQFP	PLL	Yes with Bypass
Whakaputa	LVCOS, LVDS, LVPECL, LVTTL	Ētahi Ingoa	5V9885BPFI
Tae Mahi	-40°C ~ 85°C	Tuhinga o mua	1
Momo Tae	Surface Mount	Taumata Whakaaro Moe (MSL)	3 (168 Hours)
Whakaheere Toko Whakaheere / RoHS Tūnga	Contains lead / RoHS non-compliant	Whakauru	LVCOS, LVTTL, Crystal
Tautanga - Max	500MHz	Kawewehe / Whakanao	Yes/Yes
Motuhake - Whakauru: Whakaputa	No/Yes	Tau Wae Tuakiri	IDT5V9885

Hua e Hono ana

<p>IDT5V9885BNLGI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 28-VFQFPN Tikiake: IDT5V9885BNLGI.pdf</p> <p>RFQ</p>	<p>IDT5V9352PFGI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC BUFFER ZD PLL CLK DVR 32-LQFP Tikiake: IDT5V9352PFGI8.pdf</p> <p>RFQ</p>
<p>IDT5V9885CPFGI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32TQFP Tikiake: IDT5V9885CPFGI.pdf</p> <p>RFQ</p>	<p>IDT5V9885BNLGI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 28-VFQFPN Tikiake: IDT5V9885BNLGI8.pdf</p> <p>RFQ</p>
<p>IDT5V9885BPFGI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32-TQFP Tikiake: IDT5V9885BPFGI8.pdf</p> <p>RFQ</p>	<p>IDT5V9885BPFI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32-TQFP Tikiake: IDT5V9885BPFI8.pdf</p> <p>RFQ</p>
<p>IDT5V9352PFGI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC BUFFER ZD PLL CLK DVR 32-LQFP Tikiake: IDT5V9352PFGI.pdf</p> <p>RFQ</p>	<p>IDT5V9885CNLGI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 28-VFQFPN Tikiake: IDT5V9885CNLGI8.pdf</p> <p>RFQ</p>
<p>IDT5V9885CNLGI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 28-VFQFPN Tikiake: IDT5V9885CNLGI.pdf</p> <p>RFQ</p>	<p>IDT5V9885CPFGI8 Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32-TQFP Tikiake: IDT5V9885CPFGI8.pdf</p> <p>RFQ</p>
<p>IDT5V9885BPFGI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32TQFP Tikiake: IDT5V9885BPFGI.pdf</p> <p>RFQ</p>	<p>IDT5V9885CPFI Kaihanga: IDT (Integrated Device Technology) Whakaahuatanga: IC CLK GEN 3.3V EEPROM 32-TQFP Tikiake: IDT5V9885CPFI.pdf</p> <p>RFQ</p>

Nga tohu e pa ana

IDT (Integrated Device Technology) IDT5V9885BPFI	IDT5V9885BPFI Kaitoha	IDT5V9885BPFI Kaiwhakarato
IDT5V9885BPFI Utu	IDT5V9885BPFI Nga Whakaahua	IDT5V9885BPFI Whakaahua
Pukaiti PDF IDT5V9885BPFI PDF	IDT5V9885BPFI Tangohia te Pukaiti	Pukaiti IDT5V9885BPFI
IDT5V9885BPFI Stock	Hokona IDT5V9885BPFI	Hokona IDT (Integrated Device Technology) IDT5V9885BPFI
IDT (Integrated Device Technology) IDT5V9885BPFI	IDT (Integrated Device Technology) Kaiwhakarato	Kaitoha IDT (Integrated Device Technology)
IDT (Integrated Device Technology) IDT5V9885BPFI	IDT IDT5V9885BPFI	IDT (Integrated Device Technology) IDT5V9885BPFI
IDT, Integrated Device Technology Inc IDT5V9885BPFI	Integrated Device Technology (IDT) IDT5V9885BPFI	