



HL7648_1104116

Tau Wae: **HL7648_1104116**
 Whakaahuatanga Hua: RF TXRX CELL 4G LTE CAT-1 AT&T
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Ngā Rauemi: [1.HL7648_1104116.pdf](#)
[2.HL7648_1104116.pdf](#)

Kaihanga / Waitohu: Sierra Wireless
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

[TUKUNA HE UIUI](#)

Ko te ahua he whakaahua.
 Tirohia nga whakaritenga mo nga taipitopito hua.

Taipitopito hua

| | | | |
|--|--|--|----------------------------------|
| Tau Wae | HL7648_1104116 | Kaihanga | Sierra Wireless |
| Whakaahuatanga | RF TXRX CELL 4G LTE CAT-1 AT&T | Whakahaere Toko Whakahaere / RoHS Tūnga | Whakahaerehia te kore utu / RoHS |
| Pepa Raraunga | 1.HL7648_1104116.pdf2.HL7648_1104116.pdf | | |
| Tuhinga o mua | 3.2 V ~ 4.5 V | Whakamahia IC / Wahanga | - |
| Raupapa | HL | Ngā Waehere Serial | UART, USB |
| Whakaaroaro | - | RF Family / Paerewa | Cellular |
| Tuhinga | 4G LTE CAT-1 (AT&T) | Mana - Whakaputa | - |
| Paa / Case | Module | Ētahi Ingoa | 1104116 |
| Tae Mahi | -40°C ~ 85°C | Momo Tae | Surface Mount |
| Taumata Whakaaro Moe (MSL) | 3 (168 Hours) | Whakatika | - |
| Rahi Mahara | - | Te Tae Kaituku Taeke | 12 Weeks |
| Whakahaere Toko Whakahaere / RoHS Tūnga | Lead free / RoHS Compliant | Rautanga | - |
| Raraunga Raraunga | 10Mbps | Anei - Whakawhiti | - |
| I teie nei - Te fariiraa | - | Momo Antenna | - |

Hua e Hono ana

| | |
|---|---|
| <p>HL7692_1103157 Kaihanga: Sierra Wireless Whakaahuatanga: 4G LTE CAT1 FB GPRS DUAL-BAND EU Tikiake: HL7692_1103157.pdf</p> <p>RFQ</p> | <p>HL7588_1102561 Kaihanga: Sierra Wireless Whakaahuatanga: RF TXRX 4G LTE CAT4 AT&T/VERIZON Tikiake: HL7588_1102561.pdf</p> <p>RFQ</p> |
| <p>HL7800_1103933 Kaihanga: Sierra Wireless Whakaahuatanga: MOD HL LTE CAT-M NB1 Tikiake: HL7800_1103933.pdf</p> <p>RFQ</p> | <p>HL7618_1102678 Kaihanga: Sierra Wireless Whakaahuatanga: MOD HL LTE CAT 1 Tikiake: HL7618_1102678.pdf</p> <p>RFQ</p> |
| <p>HL7588_1102748 Kaihanga: Sierra Wireless Whakaahuatanga: RF TXRX CELL 4G LTE AT&T/VERIZON Tikiake: HL7588_1102748.pdf</p> <p>RFQ</p> | <p>HL7692_1103454 Kaihanga: Sierra Wireless Whakaahuatanga: MOD HL LTE W/2G FB Tikiake: HL7692_1103454.pdf</p> <p>RFQ</p> |
| <p>HL7800_1104150 Kaihanga: Sierra Wireless Whakaahuatanga: MOD HL LTE CAT-M Tikiake: HL7800_1104150.pdf</p> <p>RFQ</p> | <p>HL7588_1102498 Kaihanga: Sierra Wireless Whakaahuatanga: RF TXRX CELLULAR 4G LTE (AT&T) Tikiake: HL7588_1102498.pdf</p> <p>RFQ</p> |
| <p>HL7618RD_1103172 Kaihanga: Sierra Wireless Whakaahuatanga: 4G LTE CAT1 MODULE VERIZON Tikiake: HL7618RD_1103172.pdf</p> <p>RFQ</p> | <p>HL7650_1103218 Kaihanga: Sierra Wireless Whakaahuatanga: 4G LTE CAT-1 3G FB AUS Tikiake: HL7650_1103218.pdf</p> <p>RFQ</p> |
| <p>HL7688_1103055 Kaihanga: Sierra Wireless Whakaahuatanga: 4G LTE CAT1 MODULE FB HSPA+ AT&T Tikiake: HL7688_1103055.pdf</p> <p>RFQ</p> | <p>HL7648_1103144 Kaihanga: Sierra Wireless Whakaahuatanga: 4G LTE CAT1 MODULE AT&T Tikiake: HL7648_1103144.pdf</p> <p>RFQ</p> |

Nga tohu e pa ana

| | | |
|--------------------------------|------------------------------------|---------------------------------------|
| Sierra Wireless HL7648_1104116 | HL7648_1104116 Kaitoha | HL7648_1104116 Kaiwhakarato |
| HL7648_1104116 Utu | HL7648_1104116 Nga Whakaahua | HL7648_1104116 Whakaahua |
| Pukaiti PDF HL7648_1104116 PDF | HL7648_1104116 Tangohia te Pukaiti | Pukaiti HL7648_1104116 |
| HL7648_1104116 Stock | Hokona HL7648_1104116 | Hokona Sierra Wireless HL7648_1104116 |
| Sierra Wireless HL7648_1104116 | Sierra Wireless Kaiwhakarato | Kaitoha Sierra Wireless |
| Sierra Wireless HL7648_1104116 | | |